

St. Mary's RC School, Gloucestershire

Location:

Bradley Stoke, Gloucestershire

Description:

The site comprises infiltration systems, wetlands, porous systems and swales. These facilities have also been used as an educational resource for the school by providing suitable habitats for a variety of wildlife and plant growth.

SuDS used:

The following SuDS components were used on this site:

Permeable pavement

Filter drains

Swales

Wetlands

[Back to case studies](#)